DAACO, INC.

Pump and Tank Contractors

5212 West Market Street

Greensboro, N.C. 27409

FEB 1 1991

Winston-Salem Regional Office

North Carolina Department of Environment, Health and Natural Resources 8025 North Point Blvd., Suite 100 Winston Salem, N.C. 27106-3295 1-21-91

RE: In Place Tank Closure at North State Telephone in High Point.

Attn: Tom Salley

Sir,

I've enclosed a plot map showing the location of both the new and original underground tanks. Soil samples were taken in June for the closure in place of the existing tank with one sample returning with a value of 16ppm. I spoke with you about the results and you suggested a site sensitivity evaluation to help determine if any remedial action was necessary. The SSE was faxed in November 15, (copies enclosed), and in a phone conversation later that day you said further remediation wouldn't be necessary.

The tank was pumped out and cleaned with county agent Terry Cole inspecting it before it was filled with hydraulic cement. The owners have placed a small building over the existing tank location and intend to install emergency switching equipment in this structure. They would like to obtain a letter of acceptance for the closure and verification that further remediation will not be necessary before permanently installing the equipment. Thank you for your time and attention on this mater. A copy of the lab analysis is attached and was obtained using the 3550 extraction method. The chain of custody was: From job site to lab, Billy Grubb

Please contact me if you have any questions.

Sincerely,

DAACO, INC.

Mames Harris

June 26, 1990

REPORT OF ANALYSIS

JOB #:

DAC@@651

CUSTOMER:

Daaco Inc

ATTN: Chip Harris

O. Q. #:

JOB 598

SAMPLE:

3123 SOIL TEST #1

3124 SOIL TEST #2

RESUL**TS**

3123

3124

Total Petroleum Hydrocarbons (ppm)

16

(10

by Method 3550

Guilford Laboratories, Inc.

i A. RayHurn

